SECTOY

photos

APR 25 1994 ]/

1. CASE NO. ALC 11 2 INDESTIGATOR'S IN									
TO THE STICK TONE OF THE CODE STICK TO THE STICK TONE OF THE CODE ST									
The state of the s									
4 DATE OF VR MO DAY 9 4 0 3 1 0	S. DATE YR MO DAY INVESTIGATION 9 4 4 0 3 2 5	INVESTIGATION REPORT							
A fine which could be a fine at the second of the second o									
damage to a kitchen has been attributed to a toaster oven having									
a defective switch. No injuries resulted from this accident.									
7. LOCATION (Name, school, etc.)  8. STATE									
Hone- Kitcheh	10 Wenham	M A							
10A FIRST PRODUCT 11A TRADE/BRAND NAME, MODEL NUMBER, MODEL BITRO20									
Toaster oven 0216 The Black & Decker Mfg. Co., Shelton, CT									
108. SECOND PRODUCT 118. TRADE/BRAND NAME, MODEL NUMBER, 06484									
cabinet 40	5 6 MANUFACTURER & ADDRESS. Un]	cnown .							
12. AGE OF VICTIM 13. SEX (Use num	erical code) 14. DISPOSITION	15. INJURY DIAGNOSIS							
UNKNOWN	No injury 0	No injury 70							
1 No.   F	7. RESPONDENT(S) (Mother, Friend) * 18. TYPE INVE	STIGATION 19. TIME SPENT							
	ieutenant, where 3 TELEPHON OTHER	E 2 3 0 7 0							
20. ATTACHMENTS	21. CASE SOURCE 22. REVIEWED BY	YR MO DAY							
Multi 9	Fire 0 1 8 3 4	2 9 4 0 4 1 5							
23. PERMISSION TO DISCLOSE NAMES	23. PERMISSION TO DISCLOSE NAMES								
(NON-NEISS CASES ONLY)	CPSC MAY DISCLOSE MY NAME CPSC	MAY NOT DISCLOSE MY NAME							
24. NARRATIVE (See Instructions on Other Side)	25. REGIONAL OFFICE	E DIRECTOR REVIEW DATE							
		5 4-18-94							
* The information contained in this report was provided by the fire									
department lieutenant and in telephone conversations with the apartment occupant and the executive director of the housing complex where this accident assured.									
where this accident occurred.									
3 8/13/19									
X									
, ad									
.•									
•									
(USE OTHER SIDE AND ADDITIONAL SHEETS IF NECESSARY)									

#### PRE-ACCIDENT:

The apartment occupant reported that she had purchased the toaster oven new at a Lechmere Sales Retail Store 7 years prior to the accident and that she had used this oven on a daily basis to bake potatoes, toast bread etc.. She also said that this toaster oven had never been damaged or repaired and had always functioned properly.

The apartment occupant reported that at approximately 0850 hours on the accident date, she toasted a piece of bread on the side in the toaster oven. She then turned the piece of bread over in the toaster oven and after closing the toaster oven door and depressing the toast switch on the oven, she placed her oven mitt on top of the oven and left her kitchen to talk on the telephone in her bedroom.

The Executive Director of the Housing Authority reported that the elderly apartment occupant is absent-minded and that her recollection of events could be unreliable. However, the apartment occupant readily answered my questions and said that she is 79 years old, in good health and has no handicaps and was not fatigued at the time of this accident.

#### ACCIDENT:

The apartment occupant reported that at approximately 0900 hours the smoke alarm in her kitchen sounded its alarm and that when she went into her kitchen, she observed that there were flames inside her toaster oven and that there was smoke in her kitchen.

#### POST-ACCIDENT:

The fire department lieutenant reported that the activation of the smoke alarm in this kitchen sounded an alarm to the fire station and that when the firemen arrived at the accident scene, they removed the toaster oven from the apartment and that no injuries resulted from this accident.

The fire department lieutenant feels that the vertical switch on the toaster oven failed, causing it to remain in the "on" position, and resulting in this accident. The elderly apartment occupant stated that she did not remove crumbs etc., from this toaster oven on a regular basis, and that she does not know why this accident occurred but that it could have been from the ignition of food materials.

#### Page 2

No injuries resulted from this accident, which caused approximately \$500.00 damage. This accident occurred at a housing complex for the elderly, which is approximately 20 years old. It was reported that this complex has copper wiring and that there are no GFCI's in the kitchen at this complex. It could not be determined if the circuit-breaker protecting the circuit into which the toaster oven was plugged, had tripped during this accident.

#### STANDARDS INFORMATION:

This toaster oven bears the following labeling "UL toaster listed 228E".

#### SAMPLES COLLECTED:

The toaster oven which was involved in this accident was collected from the local fire lieutenant (S-800-1305) and has been forwarded to CECA.

#### PRODUCT IDENTIFICATION:

The toaster oven which was involved in this accident is labeled in part "Black & Decker Model No. BITR020 Shelton Conn. \*\*\*120 volts 1500 watts 50-60 Hz A.C. only Household use Only UL TOASTER LISTED 228E". It has an approximately 2' long 2 conductor cord which is imprinted in part, "TYPE HPN HEATER CORD C+ M" with a molded plug that is imprinted "D Victor 9".

The occupant of the apartment where this fire occurred reported that this oven had been purchased new and had always functioned properly. This toaster oven was found to have a broken window (See Exhibit 3-oven Photograph 1) and the metal cross support above the upper oven carod was found to be distorted (See Exhibit 3 Photograph 10).

This toaster oven has three sets of controls on its front (See Exhibit 3-Photograph 6). One control for baking can be set on OFF 200 DEFROST 300 400 or 500. A second control is a vertical on-off switch for toasting and the third control can be set for toasting light to dark.

#### Page 3

#### ATTACHMENTS:

Attached to this report as exhibits are-

Exhibit 1 Photocopy of C/R S-800-1305

Exhibit 2 Photocopy of the local fire report on this accident

Exhibit 3 Photographs (10)

Photographs 1-5 Depict the toaster oven

Photograph 6 Depicts the controls on the toaster oven

Photographs 7-9 Depict the labeling on the toaster oven

Photograph 10 Depict the distortion of the metal support above the calrod near the top of the oven.

COC/ds

940322CNE5097 ON EXHIBIT 1

U. S. CONSUMER PRODUCT SAFETY COMMISSION SAMPLE COLLECTION REPORT 2. Date Collected 3. Sample type & number Flag [XX] Physical S-800-1305 3/28/94 Documentary . . 4b. Model 4c. Code 5. Assignment ref. 4a. Product name Toaster Oven BlTR020 0216 940322CNE5097 Complete for import samples 7. MIS: 8. Hours 6. Port of Entry Activity 32721 Entry # & date Travel Country of Origin 9a. Home RO 9b. Collecting RO HSUSA code FOER FOER Customs Contact Sample Cost ll. Invoice value of lot. 12. Size of lot 10. n/c 1 toaster oven 13. Manufacturer/Kohoxxxx 14. Shipper/Foreign Mfr. 15. Dealer MANAKK XXXXXX Lt. Philip Melanson Wenham Fire Department Wenham, MA 01984 The Black & Decker Mfg.Co Shelton, CT 06484 ID# 16. Supporting documents attached: Invoice # & date: Date shipped: Shipping record # & date: Affidavid signer's name, title & date: 17. Product Identification: Toaster oven which is imprinted in part," BLACK & DECKER MODEL NO BITRO20 SHELTON, CONN MADE IN U.S.A. 120VOLTS 1500 WATTS 50-60 Hz A.C. ONLY HOUSEHOLD USE ONLY UL TOASTER LISTED 228E" This toaster oven has 3 controls; 1 to turn the oven off-on & set its temperature, 1 to turn the toaster off-on , & 1 to set the toasting time 18. Reason for collection & analysis needed FESA CPSAXX FFA Collected in conjunction with investigation 940322CNE5097, which concerned a report from the local fire department that a fire resulted from a <u>defective switch on this toaster oven.</u> 19. Summary of Field Screening: 20. Sample Size, Method of Collection: Sample consists of one toaster oven, which was collected from Lt. Philip Melanson of the Wenham Fire Departmen This toaster oven was identified as in block 21 and was then placed into a clean fiber ctn, that was then off. sealed & prepared for shipment to the CPSC sample custodian. 21. Identification on sample: 22. Identification on seal: "S-800-1305 3/28/94 CFO" "S-800-1305 3/28/94 Charles F, O'Connell" 23a. Sample delivered to: Picked up [ 23b. Date: \* [24. Orig. report/records sent to at BOS RP by United Parcel Serv. 4/12/94 FOER 25. Laboratory/Office: ESEL [ CERM HSHL CECA XX OTHER 26. Remarks: Attn Kathy Kelsey \*23b Sample was held under lock & key from the time it was off. sld, until it was picked up by UPS. 27. Related Samples: NONE 20a. Collector's name & title: 200. Collector's signature & date: Charles F. O'Connell Investigator 3/28/94 29a. Reviewer's name & title: 29b. Reviewer's signature & date: Gilbert Bodin Supv. Investigator

EXHIBITZ


# MASSACHUSETTS FIRE INCIDENT REPORT Department of Public Safety Office of the State Fire Marshal 1010 Commonwealth Avenue Boston, Massachusetts 02215


A	10 FDID# DEPARTMENT Wenham Fire Department					Revised Report			Delete Change			ORM - 32					
		ident# 4 0 0 9 1	If Expos Fire Onl	sure ly: 0	0 Date 03/10	/9 4	Day of Week:	Thrsd	ay	5	Alarm T 09:0			ival Tim 9:09		k in 9	
В	Type of Situation Found Strct Fire-Tstr Oven 11						Type of Action Taken Mutual Aid Extinguishment 1 1 Rec'd								o'd		
С	Fixed Property Use (Occupancy) 3-6 apartment units 422							ition o cont		or failure			5 2	2	Giv X N\A	/en \	
D	Correct Address Zip Code Census Tract 7 Larch Lane 216100								t O								
E	11 Occupant Name (Last, First, Mi) Telephone (508) 468-3206 Room or Apt. 7																
F	12 Owner Name (Last, First, Mi) Address Telephone (508)468-1532							532									
6	13 Method of Alarm from Public Private alarm system  Co. Inspection Shift No. Alarms 1 District 34 1 1																
H ,		No. Fire Service Personnel Responded 1 6 Responded 2 Responded Responded					paratu	12	No. Tank Resp.	cers	0	No. Other		cles	0		
		Hazardous Material Yes Substance Present? X No						Special Equipment Used?									
1		FIRE Number of SERVICE Injuries	_		per of alities	TO C		mber d jurie		0	Number Fatali			0 1	Rescues		0
ان	Mobile Property Type  Vehicle 1 Yes Estimated Total Mobile property type n/a  8 Stolen? 2 X No Dollar Loss 500.00								0 0								
	Insurance Co. Total Ins					Insurance Claim Paid											
	3D Year Make Model Color License No. VIN#(Serial No.)																
	4D If Equipment Involved Year Make Model Serial No. In Ignition Black and Deckr B1TR020																
<	Complex Apartment complex Apartment complex Apartment complex Area Of Origin Kitchen, cooking					ng ar	Equipment Involved in Ignition Portable cook/warm unit 25							on 2 5			
-	Form of Heat Ignition Heat:equip notOK Form of Material Cooking material					al Igi	nited		7 6 Type of Material Ignited Food, starch 57					57			
1		nod of Extinguishmen	t	2	Level of Fir		gin nd		mber o		ories			Construct Unprotect			ne 8
,	Extent of Flame Damage Part of rm/area of origin 2 Floor of origin			oke D	amage	mage Detector Per Not at origi				ed 2		Sprinkler Performance No equipment present 8					
	IF SMOKE SPREAD BEYOND Form of Material Generating Most Smol Cooking material					ke	Type of Material Generating Most Smoke Food, starch 57										
	WEATHER Daylight, Heavy Rain 40'- 45' F CONDITIONS						Avenue of Smoke Travel Corridor 2										
	MEMBER MAKING REPORT DATE Philip Melanson, Lieutenant 03/17/94					so ev to s	Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office, is neither intended nor implied.										
											· F.M.			1 _ Yes	2 _	No	

#### EXHIBIT 3





Photographs 1 & 2 Depict the toaster oven.






Photographs 3 & 4 Depict the toaster oven.





Photograph 5 Depicts the toaster oven.

## 940322 CNE 5097



Photograph 6 Depicts the controls on the toaster oven.




Photographs 7 & 8 Depict the labeling on the toaster oven.




のできるのでは、他は他のであるが、「の一句」とは「他のできない。 こうしんしょう にはばれるなどのなど 神経神経 (神経・)のこと

### 940322CNE5097



Photograph 9 Depicts labeling on the toaster oven.



Photograph 10 Depicts the distortion of the metal support, above the upper oven calrod from this accident.

CONSUMER PRODUC	CT INCIDENT REPORT Charlie, Consolt								
1. NAME OF RESPONDENT 2.	TELEPHONE NO. (Horne) (Work)								
LT. PHILIP MELANSON	508-468-5508								
3. STREET ADDRESS - 4.	CITY STATE ZIP CODE								
WENHAM FIRE DEPT  5. DESCRIBE ACCIDENT SITUATION OR HAZARD, INCLUDING DATA ON INJURI	WENHAM MA, 0/984 ES. (Use second page if necessary)								
1 Minary OFFICETED	THAT ON 3/10/94 THERE WAS								
A HOUSEFIRE THAT CAUSED	#5000. DAMAGE AT AN ELDERLY								
HOUSING PROJECT IN WENMAN									
CAUGED BY A DEFECTIVE	ON-OFF SWITCH IN A BURCK								
•									
+ DECKER BRAND TOASTER	OVEN.								
6. DATE OF 7. IF INJURY OR NEAR MISS, OBTAIN	8. IF VICTIM DIFFERENT FROM RESPONDENT, PROVIDE								
INCIDENT(S)  AGE 73 SEX F AND DESCRI	BE NAME								
3//0// INJURY ///	RELATIONSHIP								
9. DESCRIPTION OF PRODUCT	10. BRAND NAME								
100,000	Pincky David								
11. MANUFACTURER/DISTRIBUTOR NAME, ADDRESS & PHONE	BLACK + DECKER  12. MODEL SERIAL NO.'S								
·	SERIAL#RITROZO								
BLACK + DECKER	13. DEALER'S NAME, ADDRESS & PHONE								
	19. DEALER S ROME, ADDRESS & PRONE								
·									
•									
14. WAS THE PRODUCT DAMAGED, REPAIRED OR MODIFIED?	15. PRODUCT PURCHASED NEW USED								
YES NO IF YES, BEFORE OR AFTER THE	DATE PURCHASED AGE								
INCIDENT?	16. DOES PRODUCT HAVE WARNING LABELS?								
	IF SO, NOTE:								
17. HAVE YOU CONTACTED THE MANUFACTURER? 18. IS THE									
	PRODUCT STILL AVAILABLE? 19. MAY WE USE YOUR NAME WITH THIS REPORT?								
· •	NO YES NO								
	L HOLD ZWEEK								
FOR ADMINIS 20. DATE RECEIVED 21. RECEIVED BY (Name & Office)	STRATION USE 22. DOCUMENT NO.								
	1								
3/14/94 (, 0 (on	NELL N430047A								
23. FOLLOW-UP ACTION	5 = 7 0 4 24. PRODUCT CODE(S)								
940322CNE 3	5097 02/6								
	ENDORSER'S NAME & TITLE								
Elos/50 CACF/CF/601/10 /	4 55L								
CPSC FORM 175 (9/89)									